

# Office of the Illinois State Fire Marshal **Division of Petroleum and Chemical Safety**

1035 Stevenson Drive Springfield, IL 62703 2177851020

# Permit for Emergency Repair Request on 4/20/2023

## FOR OFFICE USE ONLY

Facility # 3035452 Permit # 00411-2023UPG Request Rec'd 04/20/2023 Amended Date Approval Date 4/20/2023 DS Permit Expires 5/2/2023

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) **OWNER OF TANKS** - Corporation, partnership, or other business

entity:

Lincoln USA, LLC 711 US Hwy 150 E Galesburg, IL 61401

Contact: Kenny Patel (309) 289-4925

(2) **FACILITY** - name and address where tanks are located:

Lincoln USA, LLC 711 US Highway 150 East Galesburg, IL 61401

Contact: Kenny Patel (309) 289-4925

# (3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 2) 10,000, (TK # 3) 6,000, (TK # 4) 4,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 2) Gasoline Regular, (TK # 3) Gasoline Mid-grade, (TK # 4) Gasoline Premium
- (e) Type of leak detection being used:

Tank: (TK # 2, 3, 4) Leak Detect - Tank - Automatic Tank Gauging Incon TS 750

Piping:

(f) Corrosion Protection being used:

Tank.

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices: (TK # 2, 3, 4) Spill Contain Device Double Wall Spill Bucket
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: We were doing NOV repairs on junction boxes by probes when we noticed holes in the black 4" nipple risers. So we also checked the sub pump and spill 4" risers. All need replaced so water doesn't get in tank etc. Tank sumps were in bad condition as well so we will replace them and reuse sump sensors and existing APT piping.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Contact Person: Robert Schafer Pipeco, Inc. 610 29th Street Phone: (563) 344-0700

Bettendorf, IA 52722 Contractor Registration # IL2034 Exp. 9/28/2024 Daniel J. Starks

Daniel Starks

**cc:** Storage Tank Safety Specialist Division File