

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov Amended FOR OFFICE USE ONLY

Facility #: 4006397
Permit #: 00631-2023UPG
Request Rec'd: 06/09/2023
Amended Date: 07/11/2023 DS
Approval Date: 06/13/2023 DS
Permit Expires: 12/13/2023

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity:

Simran Sandhu 140 Hawthrone Road Barrington Hills, IL 61744

Lake County

Contact: Haji Singh 847/757-0750

FACILITY

- name and address where tanks are located:

Gridley Phillips 66 212 W. Gridley Road Gridley, IL 61744 McLean County

Contact: Haji Sandhu 847/757-0750

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
8	Gasoline - Regular	10,000	Out of service	Federal
10	Gasoline - Premium	6,000	Out of service	Federal

Tank 8 Equipment

Equipment Type	Permit Equipment	Action	
Piping	Other Steel Riser	New	
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket	

Tank 10 Equipment

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

Summary of Work

Removing the ball float from the vent line. Digdown is needed to replace the new riser.

Vent line for regular is going to be fixed as part of this job if any issue and then testers will do the vent line testing and upload the report.

Changing the Spill buckets, drop tubes for Regular, Premuim and Diesel since the testing is failed. Digdown to the tank top is needed for finishing this.

Thank you Innovative Constructions

Special Contingencies

Amendment Reason:

Testing failed for Reagular and Premuim spill buckets

PERSON, FIRM OR COMPANY PERFORMING WORK:

Innovative Constructions Technology LLC 3112 Aviara Court

Naperville, IL 60564

Contact Person: RAMACHANDRA RAJ penumatsa Phone: 630/747-3404

Email: iconstructions81@gmail.com

Contractor License # IL002453 Exp. 2/7/2024

Sincerely, Daniel J. Starks

Daniel Starks