

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY

Facility #: 4006397
Permit #: 01037-2023UPG
Request Rec'd: 09/12/2023
Approval Date:09/12/2023 DS
Permit Expires: 03/12/2024

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS
- Corporation, partnership, or other business entity:

Simran Sandhu
140 Hawthrone Road
Barrington Hills, IL 61744
Lake County

FACILITY
- name and address where tanks are located:

Gridley Phillips 66
212 W. Gridley Road
Gridley, IL 61744
McLean County

Tanks on the Permit

Contact: Haji Singh 847/757-0750

Tank #	Product	Capacity	Tank Status	Regulated Status
9	Gasoline - Mid-grade	6,000	Out of service	Federal
10	Gasoline - Premium	6,000	Out of service	Federal
11	Diesel Fuel	10,000	Out of service	Federal

Contact: Haji Sandhu 847/757-0750

Tank 9 Equipment

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

Tank 10 Equipment

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

Tank 11 Equipment

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

Summary of Work

Overspill buckets were replaced on Permit 00631-2023UPG. Beacon will inspect and test all Double-wall Spill Buckets at site.

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:				
Beacon SSI, Inc. 10526 W. Cermak Rd Suite 302 Westchester, IL 60154	Contact Person: Patrick Ferriter Phone: 708/917-2263 Email: patrick.ferriter@beaconssi.com Contractor License # IL002336 Exp. 1/27/2025			

Sincerely, Daniel J. Starks

Daniel Starks