

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY

Facility #: 2021158
Permit #: 01109-2023UPG
Request Rec'd: 09/26/2023
Approval Date:09/26/2023 DS
Permit Expires: 03/26/2024

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity:

Villa401, Inc.

401 E. St. Charles Rd. Villa Park, IL 60181 Du Page County

Contact: Cyriac Chandy 630/673-3382

FACILITY

- name and address where tanks are located:

Angady 74, Inc. d/b/a Shell 401 E. St. Charles Rd. Villa Park, IL 60181 Du Page County

Contact: Ayman Abdelmessih 630/673-3382

Tanks on the Permit

| Tank # | Product | Capacity | Tank Status | Regulated Status |
|--------|--------------------|----------|------------------|------------------|
| 5 | Gasoline - Regular | 10,000 | Currently in use | Federal |

Tank 5 Equipment

| Equipment Type | Permit Equipment | Action |
|----------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |
| Overfill Prevention Device | Overfill Drop Tube Valve | Replacing - Overfill Prev Device - Overfill Drop Tube Valve |

Summary of Work

Drop tube was stuck into the riser. Need to replace the Spill bucket and Drop tube. Dig down is needed to the tank top

Thank you Innovative Constructions

Special Contingencies

Vaniel J. Starke

| PERSON, FIRM OR COMPANY PERFORMING WORK: | | | | |
|---|---|--|--|--|
| Innovative Constructions Technology LLC 245 W Roosevelt Rd Building 4, Unit 28 West Chicago, IL 60185 | Contact Person: Raju penumatsa Phone: 630/747-3404 Email: iconstructions81@gmail.com Contractor License # IL002453 Exp. 2/7/2024 | | | |

Sincerely,

Daniel Starks