

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY

Facility #: 2010558
Permit #: 01138-2023UPG
Request Rec'd: 10/03/2023
Approval Date:10/03/2023 DS
Permit Expires: 04/03/2024

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for</u> <u>Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity:

Sukhi Parvaar, Inc. 1056 Wrens Gate Mundelein, IL 60060

Lake County

Contact: Manjit K. Sandhu 224/715-0395

FACILITY

- name and address where tanks are located:

Berwyn Go

1337 S. Harlem Ave. Berwyn, IL 60402 Cook County

Contact: Manjit K. Sandhu 708/788-6264

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
8	Diesel Fuel	6,000	Currently in use	Federal

Dispensers on the Permit

Dispenser	Action	
13/14 Diesel	Sump / Sensors Changing	

Dispenser 13/14 Diesel Equipment

Equipment Type	Permit Equipment	Action
Dispenser	Single Wall UDC Sump	Replacing - Dispenser - Single Wall UDC Sump
►Leak Detection - Piping	Sump Sensor with positive shutdown	Reusing Existing

Summary of Work

Replace Existing Diesel UDC with new Bravo Single Wall UDC with entry boot and stabilizer bar. Reuse existing product piping Hand Form new island Install new U Shaped Bollard Reason for work existing sump will not pass Hydrostatic test

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:			
Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108	Contact Person: Robert Stenstrom Phone: 708/243-0193 Email: dough@rstenstrom.com Contractor License # IL1890 Exp. 4/12/2024		

Sincerely, Daniel J. Starks

Daniel Starks