



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY

Facility #: 6032263
Permit #: 01490-2023UPG
Request Rec'd: 12/20/2023
Approval Date: 12/20/2023 DS
Permit Expires: 06/22/2024

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Shrea Umiya Mataji, Inc. 301 Southport Drive Columbia, IL 62236 Monroe County Contact: Sanjay Patel 618/281-5858	FACILITY - name and address where tanks are located: Red Roof Liquor and Lottery, Inc. 301 Southport Drive Columbia, IL 62236 Monroe County Contact: Sanjay Patel 618/281-5858
--	---

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
1	Gasoline - Regular	12,000	Currently in use	Federal
2	Gasoline - Premium	6,000	Currently in use	Federal
3	Diesel Fuel	6,000	Currently in use	Federal

Tank 1 Equipment

Equipment Type	Permit Equipment	Action
Leak Detection - Tank	Hydrostatic Reservoir Interstitial Monitoring Sensors with monitor	Replacing - Leak Detect - Tank - Hydrostatic Reservoir Interstitial Monitoring Sensors
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket
Overfill Prevention Device	Overfill Drop Tube Valve	Replacing - Overfill Prev Device - Ball Float Vent Valve Universal 37

Tank 2 Equipment

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket
Overfill Prevention Device	Overfill Drop Tube Valve	Replacing - Overfill Prev Device - Ball Float Vent Valve Universal 37
Leak Detection - Tank	Hydrostatic Reservoir Interstitial Monitoring Sensors with monitor	Replacing - Leak Detect - Tank - Hydrostatic Reservoir Interstitial Monitoring Sensors

Tank 3 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Overfill Drop Tube Valve	Replacing - Overfill Prev Device - Ball Float Vent Valve Universal 37
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket
Leak Detection - Tank	Hydrostatic Reservoir Interstitial Monitoring Sensors with monitor	Replacing - Leak Detect - Tank - Hydrostatic Reservoir Interstitial Monitoring Sensors


Summary of Work

installing doublwall spill buckets and overfill drop tubes on all three tanks. wiring interstitial sensors and dispenser sump sensors to ATG,

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:	
UPC Enterprises, LC d/b/a United Petroleum Service 128 Millwell Drive Maryland Heights, MO 63043	Contact Person: Terry Smith Phone: 314/797-0468 Email: cbayne@unitedpetro.com Contractor License # IL002402 Exp. 2/10/2024

Sincerely,



Daniel Starks