

Division File (Rev. - 1/98)

(1) **OWNER OF TANKS** - Corporation, partnership, or other

## OFFICE OF THE ILLINOIS STATE FIRE MARSHAL

**Division of Technical Services** 

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)524-7605

## Amended

FOR OFFICE USE ONLY

Facility # 2-018522
Permit # 01040-2006UPG
Request Rec'd 07/10/2006
Amended Date 08/28/2006
Approval Date 7/19/2006 JC
Permit Expires 1/19/2007

(2) **FACILITY** - name and address where tanks are located:

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Part 170. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE**.

business entity:	
Oak Forest Hospital of Cook County	Oak Forest Hospital
118 N Clark St	15900 S Cicero Ave
Chicago, IL 60602-5671	Oak Forest, Cook Co., IL
Contact: Steven Szany (708) 633-2319	Contact: Radich Thomas (708) 687-7200
3) <u>UPGRADE OR REPAIR OF TANKS:</u>	
(a) Number and size of tanks being upgraded or repaired: (The	ζ # 7, 8) - 2,500 gallons
(b) Type of tanks: (TK # 7, 8) - Existing double wall fiberglass	
(c) Type of piping: (TK # 7, 8) - Existing single wall fiberglass	
(d) Product to be stored in each tank: (TK # 7, 8) - Diesel Fue	1
(e) Type of leak detection being used:	
Tank: (TK # 7, 8) - Existing automatic tank gauging, (TK	(L # 7, 8) - (Installing) Veeder Root TLS 300c interstitial tank sensor
<i>Piping:</i> (TK # 7, 8) - Existing European Suction	
(f) Corrosion Protection being used:	
Tank:	
<b>Piping:</b> (TK # 7, 8) - Existing fiberglass	
(g) Spill containment devices:	
(h) Overfill prevention devices:	
(i) Manway accessible at grade:	
Form and the licensed contractor must submit the required job sche	repair has occurred, on the Notification for Underground Storage Tank dule for underground piping upgrade, leak detection, spill and overfill orms can be obtained at <a href="https://www.state.il.us/osfm">www.state.il.us/osfm</a> or by calling (217)785-1020.
5) SPECIAL CONTINGENCIES:	_
(6) PERSON, FIRM OR COMPANY PERFORMING WORK:	
· ·	Contact Person:
	Phone:
<del></del>	Contractor Registration # Exp.
Sincerely,	
Jim Coffey	
c: Storage Tank Safety Specialist -	
Fire Department - Office Coordinator -	
Office Coordinator -	