



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov
Amended

FOR OFFICE USE ONLY

Facility #: 3034560
Permit #: 00142-2024UPG
Request Rec'd: 02/06/2024
Amended Date: 02/09/2024 SB
Approval Date: 02/06/2024 DS
Permit Expires: 08/06/2024

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Casey's Retail Company 3305 SE Delaware Ave. P.O. Box 3004 Ankeny, IA 50021 Contact: Lee Lytle 515/446-6231	FACILITY - name and address where tanks are located: Casey's #4506 403 S. 4th Street 13821 N. Route 91 Dunlap, IL 61525 Peoria County Contact: Jill Reams-Widder 515/446-6238
--	--

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
1	Gasoline - Regular	10,000	Currently in use	Federal

Tank 1 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Overfill Drop Tube Valve	Replacing - Overfill Prev Device - Overfill Drop Tube Valve
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket
Overfill Prevention Device	Ball Float Vent Valve	Removing

Summary of Work

T1 Single wal spill basin failed the compliance test along with T1 overfill valve. We will replace the spill basin with a new Double wall Franklin Fueling Defender spill and a franklin overfill valve. T2 & T3 & T4 Ball float vent valve failed the compliance test as well. We removed the ball floats and installed new Franklin Fueling Defender overfill valves in the existing spill basins.

Special Contingencies

Amendment Reason:

We could not remove the drop tube from the tank #4 6000 DSL to install a new overfill valve so we had to replace the single wall spill with a new Franklin Fueling Double Wall spill.

2nd Amendment: Forgot to include the ball float as being removed on tank #1

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Pipeco, Inc. 610 29th Street Bettendorf, IA 52722	Contact Person: Robert Schafer Phone: 563/529-8502 Email: rob@pipecoinc.com Contractor License # IL2034 Exp. 9/28/2024

Sincerely,

Daniel G. Starks

Daniel Starks