

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov

#### FOR OFFICE USE ONLY

Facility #: 3043826
Permit #: 00205-2024UPG
Request Rec'd: 02/21/2024
Approval Date:02/21/2024 DS
Permit Expires: 08/21/2024

# <u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

#### THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

(None) County

- Corporation, partnership, or other business entity:

Moline Freight, LLC 101 First Street, Suite 450 Los Altos, CA 940222750

Contact: Shelley Detrick 650/917-8500

**FACILITY** 

- name and address where tanks are located:

FedEx Freight, Inc.-RKI 5035 Morton Drive East Moline, IL 612449549 Rock Island County

Contact: Ralph Martinez 870/365-4087

#### Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
2	Diesel Fuel	20,000	Currently in use	Federal

### **Tank 2 Equipment**

<b>Equipment Type</b>	Permit Equipment	Action
Leak Detection - Tank	Non-Discriminating Interstitial Monitoring Sensors	Replacing - Leak Detect - Tank - Non-Discriminating Interstitial Monitoring Sensors
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

#### **Summary of Work**

Replace existing spill bucket on tank 2 with OPW 1C-3112D dw spill bucket. Replacing interstitial monitor on tank 2.

#### **Special Contingencies**

Vaniel J. Starke

PERSON, FIRM OR COMPANY PERFORMING WORK:

Seneca Companies, Inc.
4140 East 14th Street PO Box 3360
Des Moines, IA 50313

Contact Person: Glen Davis
Phone: 563/468-0900
Email: jlundquist@senecaco.com
Contractor License # IL598 Exp. 2/23/2024

Sincerely,

**Daniel Starks**