



**Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety**  
1035 Stevenson Drive  
Springfield, IL 62703  
217/785-1020  
www.sfm.illinois.gov  
SFM.DPCS@illinois.gov  
**Amended**

**FOR OFFICE USE ONLY**  
Facility #: 2039058  
Permit #: 00089-2024UPG  
Request Rec'd: 01/25/2024  
Approval Date: 01/25/2024 DS  
Amended Date: 03/13/2024 DS  
Permit Expires: 07/25/2024

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for  
Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

**THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

|   |   |
|---|---|
| <b>OWNER OF TANKS</b><br>- Corporation, partnership, or other business entity:<br>Drendel Enterprises LLC<br>13280 South Illinois Route 47<br>Huntley, IL 60142<br>Kane County<br>Contact: James Drendel 815/455-7240 | <b>FACILITY</b><br>- name and address where tanks are located:<br>Drendel's Corner, Inc.<br>13280 South Illinois Route 47<br>Huntley, IL 60142<br>McHenry County<br>Contact: James Drendel 815/455-7240 |
|---|---|

**Tanks on the Permit**

| Tank # | Product            | Capacity | Tank Status      | Regulated Status |
|--------|--------------------|----------|------------------|------------------|
| 1      | Gasoline - Premium | 15,000   | Currently in use | Federal          |
| 2      | Gasoline - Regular | 20,000   | Currently in use | Federal          |

**Tank 1 Equipment**

| Equipment Type             | Permit Equipment         | Action   |
|----------------------------|--------------------------|--|
| Overfill Prevention Device | Overfill Drop Tube Valve | Replacing - Overfill Prev Device - Ball Float Vent Valve OPW 53VML |
| Spill Containment Device   | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket        |

**Tank 2 Equipment**

| Equipment Type             | Permit Equipment         | Action   |
|----------------------------|--------------------------|--|
| Overfill Prevention Device | Overfill Drop Tube Valve | Replacing - Overfill Prev Device - Ball Float Vent Valve OPW 53VML |
| Spill Containment Device   | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket        |

**Summary of Work**

Replace both ball floats and replace with drop tubes. Drop tubes to be set to 95% fill capacity  
Replace PUL and RUL vapor risers  
Replace PUL and RUL fill risers  
Upgrade to DW spill buckets

**Special Contingencies**

**Amendment Reason:**


Customer requests replacement of both vapor risers and both fill risers on site. This includes spill bucket upgrades.

**PERSON, FIRM OR COMPANY PERFORMING WORK:**

Stenstrom Petroleum Services Group  
2422 Center Street  
Rockford, IL 61108

Contact Person: Robert Stenstrom  
Phone: 815/520-5292  
Email: trevorh@rstenstrom.com  
Contractor License # IL1890 Exp. 4/12/2024

Sincerely,



---

Daniel Starks