



**Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety**

1035 Stevenson Drive  
Springfield, IL 62703  
217/785-1020  
www.sfm.illinois.gov  
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY	
Facility #:	2037427
Permit #:	00884-2024UPG
Request Rec'd:	07/22/2024
Approval Date:	07/25/2024 DS
Permit Expires:	01/27/2025

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

**THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

OWNER OF TANKS - Corporation, partnership, or other business entity:	FACILITY - name and address where tanks are located:
Chemung Country Store Inc 24102 Rt 173 Chemung, IL 60033 McHenry County Contact: Robert A Kerton 815/943-3115	Chemung Country Store, Inc. 24102 Rt. 173 Chemung, IL 60033 McHenry County Contact: Kathy Wisowaty 815/943-3115

**Tanks on the Permit**

Tank #	Product	Capacity	Tank Status	Regulated Status
2	Gasoline - Premium	8,000	Currently in use	Federal

**Tank 2 Equipment**

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket
Piping	Fiberglass Single Wall Piping Ameron Dualoy 3000/L	Replacing - Piping - Fiberglass Single Wall Piping Ameron

**Summary of Work**

It was detected by testing company that the existing Premium on the Northside if dispenser island 3&4 had a leak and it was located using helium trace.

We will expose line and make repair to singlewall Ameron line, test and inspect. Backfill and pour concrete. 3rd party line test afterwards.

Also teh overfill drop tube could not be removed at time of inspection so we will attempt to remove and inspect for proper operation. If we can not remove we will replace overspill with new OPW 1C3112P doublewall overspill, new 4" riser and coaxial overfill drop tube at same time as line repair

**Special Contingencies**

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108	Contact Person: Robert Stenstrom Phone: 708/243-0193 Email: dough@rstenstrom.com Contractor License # IL1890 Exp. 4/12/2026

Sincerely,

Daniel Starks