

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov Amended

 FOR OFFICE USE ONLY

 Facility #:
 3007074

 Permit #:
 00966-2024UPG

 Request Rec'd:
 08/12/2024

 Approval Date:
 08/12/2024 DS

 Amended Date:
 08/19/2024 DS

 Permit Expires:
 02/13/2025

# Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

## THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity:	FACILITY - name and address where tanks are located:
Global One Properties, Inc. 1930 W. Forest Hill Ave. Peoria, IL 61604 Peoria County	Fuel Zone Synergy, Inc. 1930 W. Forrest Hill Ave. Peoria, IL 61604 Peoria County
Contact: Atick Sanany 309/244-5290	Contact: Atick Sanany 309/244-5290

### **Tanks on the Permit**

Tank #	Product	Capacity	Tank Status	<b>Regulated Status</b>
2	Gasoline - Regular	10,000	Currently in use	Federal
3	Gasoline - Premium	10,000	Currently in use	Federal

## Tank 2 Equipment

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

## **Tank 3 Equipment**

Equipment Type	Permit Equipment	Action
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

#### Summary of Work

Replacing damaged single wall spill containment with new double wall spill containment.

#### **Special Contingencies**

#### Amendment Reason:

Need to replace spill manhole on ID #3 due to manhole being in disrepair. Found issue while replacing spill manhole on ID #2.

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Total Petroleum Service Company 2421 Washington Road Washington, IL 61571	Contact Person: Cheri McCoy Phone: 309/694-8224 Email: Tom.Oltman@TotalPetroleum.net Contractor License # IL1079 Exp. 2/8/2026

Sincerely, Daniel J. Starks

Daniel Starks