



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY
Facility #: 3007068
Permit #: 01007-2024ABN
Request Rec'd: 08/16/2024
Approval Date: 08/19/2024 DS
Permit Expires: 02/19/2025

Permit for ABANDONMENT-IN-PLACE of Underground Storage Piping for Petroleum and Hazardous Substances

Permission to abandon- in- place underground storage tank piping is hereby granted. Such abandonment must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175, and 176. The contractor the permit was issued to shall establish a date certain to perform the UST activity by shall establish a date certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account If the Storage Tank Safety Specialist (STSS) observes evidence of a release, the owner, operator or designated representative of the UST owner/operator must notify the Illinois Emergency Management Agency (IEMA). The incident number shall be given to the STSS prior to his/her leaving the site.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Morton Gas Company II 400 West Birchwood Morton, IL 61550 Tazewell County Contact: Ashraf Sayeed 630/205-6372	FACILITY - name and address where tanks are located: Morton Gas Company II 400 West Birchwood Morton, IL 61550 Tazewell County Contact: Ashraf Sayeed 309/550-5150
---	---

Tanks on the Permit For Piping Only

Tank #	Capacity	Product	Fill Material	Comments
3	10,000	Diesel Fuel	Piping Capped Off	

Explanation of Waiver for Abandonment

Abandonning approximately 20' of single wall frp pipe. Helium test revealed a leak at dispenser 7/8. Uncovered piping, found a buried flexible connector leaking. Cut out flex connector and capped portion of line feeding dispenser 3/4. Plugged end of piping tee feeding dispenser #7/8. Unable to replace piping where flex was removed due to differences in piping elevations which is why flex was installed originally. Performing precision test on remaining product line.

Location of Piping Being Abandoned

Piping being abandoned shares a trench with active piping and cannot be removed.

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Total Petroleum Service Company 2421 Washington Road Washington, IL 61571	Contact Person: Cheri McCoy Phone: 309/694-8224 Email: Tom.Oltman@TotalPetroleum.net Contractor License # IL1079 Exp. 2/8/2026

Sincerely,



Daniel Starks