



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL
Division of Technical Services
1035 Stevenson Drive
Springfield, Illinois 62703-4259
(217)524-7605

FOR OFFICE USE ONLY
Facility # 7-021606
Permit # 00944-2006LIN
Request Rec'd 06/21/2006
Amended Date
Approval Date 7/3/2006 JC
Permit Expires 7/3/2007

Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity: Knapp Oil Co., Inc. 524 Front Street, P.O. Box 215 Xenia, IL 62899 Contact: Bill Knapp (618) 678-2211	(2) FACILITY - name and address where tanks are located: Xenia Union 76 1500 Church Street Xenia, Clay Co., IL Contact: Bill Knapp (618) 678-2800
---	--

(3) INSPECTION OF INTERIOR LINING OF TANKS:

- (a) Number and size of tanks being inspected:* (TK # 1) - 6,000 gallons, (TK # 2) - 10,000 gallons
- (b) Type of tanks:* (TK # 1, 2) - Existing single wall steel
- (c) Product stored in each tank:* (TK # 1, 2) - Gasoline
- (d) Manway accessible at grade:*

(4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.

(5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.state.il.us/osfm or by calling (217)785-1020.

(6) SPECIAL CONTINGENCIES: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). Extension request letter received 12/29/06. Tanks 1 & 2 were originally lined 10/08/96; they have been using monthly inventory control for the sole method of tank release detection since the original registration in 1986. An alternate method of tank release detection will be due by 10/09/06 - see 170 regulations section 170.530 (I). Also, according to our records, tank #4 was installed 02/22/05 and was incorrectly permitted to use monthly inventory control as a sole method for tank release detection. After consulting with Dale Tanke (07/02/06 11:30) on this issue it has been determined that tank #4 will also have to change to an alternate form of tank release detection. Section 170.530 (J) of the Part 170 regulations does not allow for new tanks installed after May 1, 2003 to use monthly inventory control.

<u>(7) PERSON, FIRM OR COMPANY PERFORMING WORK:</u> Bolin Enterprises, Inc. P.O. Box 70, _____	Contact Person: James Bolin Phone: _____ Contractor Registration # _____ Exp. _____
--	---

Sincerely,

cc: Storage Tank Safety Specialist -
Fire Department -
Office Coordinator -
Division File
(Rev. - 1/98)