

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov

 FOR OFFICE USE ONLY

 Facility #:
 2045852

 Permit #:
 00230-2025UPG

 Request Rec'd:
 02/27/2025

 Approval Date:02/27/2025 DS
 DS

 Permit Expires:
 08/27/2025

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity:	FACILITY - name and address where tanks are located:
Murphy Oil USA, Inc. 200 E. Peach Street El Dorado, AR 71730 (None) County	Murphy USA #7581 2676 IL Route 83 Round Lake Beach, IL 60073 Lake County
Contact: John Moore 870/677-6116	Contact: Margie Graham 870/875-7610

Tanks on the Permit

Tank	# Prod	uct Capaci	ty Tank Statu	s Regulated Status
2	Gasoline -	Premium 8,000	Currently in u	ise Federal

Tank 2 Equipment

Equipment Type	Permit Equipment	Action	
Overfill Prevention Device	Overfill Drop Tube Valve	Replacing - Overfill Prev Device - Overfill Drop Tube Valve	
Piping	Other Steel Riser - Replacing vapor riser	New	
Piping Other Steel Riser - Replacing fill riser		New	
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Double Wall Spill Bucket	

Summary of Work

Site can not get fuel drops due to the condition of the fill riser, adapter, overfill drop tube and overspill bucket on the Premium tank # 2. Installing new fill riser, overspill bucket, overfill drop tube, adapter, cap, due to proximity of fill installing new vapor riser, vapor bucket, adapter and cap on Premium tank # 2.

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:			
Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448	Contact Person: Ron Anderson Phone: 708/560-5590 Email: keith@andersonpump.com Contractor License # IL002275 Exp. 5/21/2026		

Sincerely,

Jamiel J. Starke

Daniel Starks