



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov
Amended

FOR OFFICE USE ONLY
Facility #: 2007105
Permit #: 00932-2025UPG
Request Rec'd: 07/20/2025
Approval Date: 07/21/2025 DS
Amended Date: 07/28/2025 SB
Permit Expires: 01/21/2026

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Sunny Peters 1801 E Sauk Trail Sauk Village, IL 60411 (None) County Contact: Sunny Peters 630/674-7869	FACILITY - name and address where tanks are located: Sauk Trail Food Mart 1801 E. Sauk Trail Sauk Village, IL 60411 Cook County Contact: Sunny Peters 630/674-7869
--	---

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
4	Gasoline - Premium	10,000	Currently in use	Federal

Tank 4 Equipment

Equipment Type	Permit Equipment	Action
Piping	Fiberglass Single Wall Piping A.O. Smith	New
Piping	Other Steel Riser	New

Summary of Work

Premium tank getting water, Checked spill bucket riser (not getting water), checked vapor extractor and vapor recovery riser (not getting water), check probe riser (not getting water), opened a closed riser and found water getting into the tank, replacing that riser with new riser followed with tank tightness testing.

Special Contingencies

Amendment Reason:

We found riser getting water in the tank, when we dig down we found vapor extractor and found vent SW fiberglass VENT line damaged and competly disconnected. Installing new 23' SW fiberglass vent line for premium tank followed with air test.

PERSON, FIRM OR COMPANY PERFORMING WORK:	
American Petroleum Solutions LLC 2911 Lund avenue apt 8 Rockford, IL 61109	Contact Person: Haibat Khan Phone: 909/312-9449 Email: apetro.office@gmail.com Contractor License # IL002454 Exp. 5/21/2026

Sincerely,

Daniel Starks