



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov
Amended

FOR OFFICE USE ONLY
Facility #: 2045553
Permit #: 01088-2025UPG
Request Rec'd: 08/20/2025
Approval Date: 08/20/2025 DS
Amended Date: 08/21/2025 DS
Permit Expires: 09/03/2025

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: RDK Ventures, LLC 1120 W. Warner Rd. Tempe, AZ 85284 (None) County Contact: Michele Alvarado 773/456-5280	FACILITY - name and address where tanks are located: Circle K #6799 7050 S. Harlem Avenue Bridgeview, IL 60455 Cook County Contact: Gracie Janik 708/594-1430
---	--

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
1	Diesel Fuel	20,000	Currently in use	Federal

Tank 1 Equipment

Equipment Type	Permit Equipment	Action
Piping	Fiberglass Double Wall Ameron Dualoy 3000/LCX	Replacing - Piping - Fiberglass Double Wall A.O. Smith
Piping	Flex Connector Steel	New

Summary of Work

Portal has no options for the specific work being done... Anderson is replacing the "hard steel" piping, nipples, fittings on Dispenser 21 Slave that are leaking. We are not replacing the flex connector (re-using existing), nor are we repalcing the sump sensor. No work is being done on Dispenser 21 Master. ADDITIONAL WORK BEING ADDED TO INITIAL PERMIT = Replacing 3 ft - 5 ft of Fiberglass Double Wall Ameron Dualoy 3000/LCX product pipe for Diesel Tank# 1 that feeds Master Dispenser 21.

Special Contingencies

Amendment Reason:

Need to replace 3 ft - 5 ft of Fiberglass Double Wall Ameron Dualoy 3000/LCX pipe (For Tank# 1 Diesel) feeding the Master 21 Dispenser

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448	Contact Person: Ron Anderson Phone: 708/560-5590 Email: Keith@Andersonpump.com Contractor License # IL002275 Exp. 5/21/2026

Sincerely,

Daniel J. Starks

Daniel Starks