



**Office of the Illinois State Fire Marshal**  
**Division of Petroleum and Chemical Safety**  
 1035 Stevenson Drive  
 Springfield, IL 62703  
 217/785-1020  
 www.sfm.illinois.gov  
 SFM.DPCS@illinois.gov

<b>FOR OFFICE USE ONLY</b>	
Facility #:	2031654
Permit #:	00399-2026UPG
Request Rec'd:	04/02/2026
Approval Date:	04/12/2026 DS
Permit Expires:	10/14/2026

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

**THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

<b>OWNER OF TANKS</b> - Corporation, partnership, or other business entity: Bryn Mawr Country Club 6600 North Crawford Avenue Lincolnwood, IL 60712 Cook County Contact: Brian A Bossert 847/677-4112	<b>FACILITY</b> - name and address where tanks are located: Bryn Mawr Country Club 4340 West Devon Lincolnwood, IL 60712 Cook County 10-34-400-001-0000 Contact: Brian A Bossert 847/677-4112
---	--

**Tanks on the Permit**

Tank #	Product	Capacity	Tank Status	Regulated Status
2	Diesel Fuel	660	Currently in use	Federal
3	Gasoline - Regular	660	Currently in use	Federal

**Tank 2 Equipment**

Equipment Type	Permit Equipment	Action
Leak Detection - Tank	Hydrostatic Reservoir Interstitial Monitoring Sensors	Replacing - Leak Detect - Tank - Non-Discriminating Interstitial Monitoring Sensors

**Tank 3 Equipment**

Equipment Type	Permit Equipment	Action
Leak Detection - Tank	Hydrostatic Reservoir Interstitial Monitoring Sensors	Replacing - Leak Detect - Tank - Non-Discriminating Interstitial Monitoring Sensors

**Summary of Work**

Beacon is converting the Interstice on both tanks to Brine-filled Interstice as the tanks were originally designed to be. We will install Dual Float Hydrostatic Sensors.

**Special Contingencies**

<b>PERSON, FIRM OR COMPANY PERFORMING WORK:</b>	
Beacon SSI, Inc. 10526 W. Cermak Rd Suite 302 Westchester, IL 60154	Contact Person: Patrick Ferriter Phone: 708/917-2263 Email: patrick.ferriter@beaconssi.com Contractor License # IL002336 Exp. 1/27/2027

Sincerely,

*Daniel J. Starks*

Daniel Starks