



**OFFICE OF THE ILLINOIS STATE FIRE MARSHAL**  
**Division of Technical Services**  
 1035 Stevenson Drive  
 Springfield, Illinois 62703-4259  
 (217)524-7605

FOR OFFICE USE ONLY  
 Facility # 2-000496  
 Permit # 01371-2006LIN  
 Request Rec'd 09/14/2006  
 Amended Date  
 Approval Date 9/15/2006 JC  
 Permit Expires 3/15/2007

**Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.**

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

**THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

<p><b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity:          Baron Huot Oil Co          1 Bradford Place, P.O. Box 517          Bradley, IL 60915          Contact: Jerry Huot (815) 933-3365</p>	<p><b>(2) FACILITY</b> - name and address where tanks are located:          Lincolnshire 66          1590 W. Court Street &amp; Curtis Ave.          Kankakee, Kankakee Co., IL          Contact: Hoot Jerry (815) 933-3365</p>
--	---

**(3) INSPECTION OF INTERIOR LINING OF TANKS:**

- (a) *Number and size of tanks being inspected:* (TK # 1) - 6,000 gallons, (TK # 2) - 8,000 gallons, (TK # 3) - 4,000 gallons
- (b) *Type of tanks:* (TK # 1, 2, 3) - Existing single wall steel
- (c) *Product stored in each tank:* (TK # 1, 2, 3) - Gasoline
- (d) *Manway accessible at grade:*

- (4) **Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.**
- (5) **The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at [www.state.il.us/osfm](http://www.state.il.us/osfm) or by calling (217)785-1020.**
- (6) **SPECIAL CONTINGENCIES:** Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). Tanks were originally lined sometime in 1989. These tanks were possibly inspected at a later date; however, we have no field notes, measurements, or any other data concerning the "possible" inspection (except for a short note on a certification audit received 05/03/04, and a letter from Armor Shield stating an inspection was done at some point). Tanks may also have sacrificial anodes. See contingencies section from permit #00116-2006CAT for further details.

<p><b>(7) PERSON, FIRM OR COMPANY PERFORMING WORK:</b></p>	
<p>Bolin Enterprises, Inc.          P.O. Box 70,</p>	<p>Contact Person: James Bolin          Phone:          Contractor Registration #    Exp.</p>

Sincerely,

cc: Storage Tank Safety Specialist -  
 Fire Department -  
 Office Coordinator -  
 Division File  
 (Rev. - 1/98)