



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL
Division of Technical Services
1035 Stevenson Drive
Springfield, Illinois 62703-4259
(217)524-7605

FOR OFFICE USE ONLY
Facility # 2-021384
Permit # 00481-2006LIN
Request Rec'd 04/04/2006
Amended Date
Approval Date 4/5/2006 JC
Permit Expires 10/5/2006

Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Part 170. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity: SRJ Associates 6335 Dempster Morton Grove, IL 60053 Contact: Stanly Matthews (847) 877-3316	(2) FACILITY - name and address where tanks are located: GoTane Citgo Station 6335 Dempster Morton Grove, Cook Co., IL Contact: Stanley Matthews (847) 877-3316
---	--

(3) INSPECTION OF INTERIOR LINING OF TANKS:

- (a) Number and size of tanks being inspected:* (TK # 1) - 10,000 gallons
- (b) Type of tanks:* (TK # 1) - Existing single wall steel
- (c) Product stored in each tank:* (TK # 1) - Gasoline
- (d) Manway accessible at grade:*

(4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.

(5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.state.il.us/osfm or by calling (217)785-1020.

(6) SPECIAL CONTINGENCIES: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by sections 170.430(a)(1)(C) and (D), 170.430(b)(5), and 170.430(c)(10). Tank #1 was probably lined in 1989 or 1990 from permit #1370 REL; however, there is no log or notification form to verify if it was done. If it was lined at that time, then it is at least 6 years past due for an inspection (there is no other corrosion protection for the tank). Also, the overfill protection must be field verified for tank #1 & #5. These tanks originally had a ball float valve. Also, permit #4949-98UPG was to install overfill alarms, but then it was amended to install drop tube valves only (this was because the contractor said the existing system was not compatible with an overfill alarm). The problem is, later certification audits and the permit log shows an overfill alarm was installed. A Timely Compliance Opportunity letter was issued for this site on 03/07/06 allowing this facility 60 days to come into compliance. If compliance is not achieved by 05/06/06 the non-compliant underground storage tank(s) will be red-tagged.

(7) PERSON, FIRM OR COMPANY PERFORMING WORK:

Bolin Enterprises, Inc.
P.O. Box 70,

Contact Person: James Bolin
Phone:

Contractor Registration # Exp.

Sincerely,

cc: Storage Tank Safety Specialist -
Fire Department -
Office Coordinator -
Division File
(Rev. - 1/98)