



OFFICE OF THE ILLINOIS STATE FIRE MARSHAL  
Division of Technical Services  
1035 Stevenson Drive  
Springfield, Illinois 62703-4259  
(217)524-7605

FOR OFFICE USE ONLY  
Facility # 2-016651  
Permit # 01288-2010LIN  
Request Rec'd 11/15/2010  
Amended Date  
Approval Date 11/15/2010 JC  
Permit Expires 5/15/2011

**Permit for INSPECTION OF INTERIOR LINING of Underground Storage Tank(s) for Petroleum and Hazardous Substances.**

Permission to inspect existing interior lining of underground storage tank(s) is hereby granted. Such inspections of interior lining must be in complete accordance with all sections and procedures specified in 41 Illinois Administrative Code, Parts 174, 175 and 176. Such inspections of interior lining shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled.

**THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

<b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity:  Thomas Leach Sr. 255 S. West Avenue #5 Elmhurst, IL 60126  Contact: Tom Leach Sr. (708) 834-0481	<b>(2) FACILITY</b> - name and address where tanks are located:  Gas Stop 575 South York Road Elmhurst, Du Page Co., IL  Contact: Tom Leach (630) 834-1700
---	--

**(3) INSPECTION OF INTERIOR LINING OF TANKS:**

- (a) Number and size of tanks being inspected:** (TK # 3) - 6,000 gallons
- (b) Type of tanks:**
- (c) Product stored in each tank:** (TK # 3) - Gasoline
- (d) Manway accessible at grade:** Contractor states there is not an existing bolted manway. He also does not state whether or not one will be installed.

- (4) Any tank that has been out of service for a twelve-month consecutive period cannot be put back into service unless it meets all new UST upgrade regulations. This permit is for the inspection of the existing interior lining only. No repairing, upgrading, or interior lining is authorized with this permit.**
- (5) The owner must notify this Office when completion of tank interior inspection has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.**

- (6) SPECIAL CONTINGENCIES: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by section 175.500. Contractor states there is not an existing bolted manway. He also does not state whether or not one will be installed.**

<b>(7) <u>PERSON, FIRM OR COMPANY PERFORMING WORK:</u></b>  Armor Shield Of Wisconsin 4623 Hillcrest Parkway Slinger, WI 53086	Contact Person: George Bennett Phone:  Contractor Registration #    Exp.
--	---

Sincerely,

cc: Storage Tank Safety Specialist -  
Fire Department -  
Office Coordinator -  
Division File  
(Rev. - 9/10)