



**OFFICE OF THE ILLINOIS STATE FIRE MARSHAL**  
**Division of Petroleum and Chemical Safety**  
 1035 Stevenson Drive  
 Springfield, Illinois 62703-4259  
 (217)785-1020

|                            |
|----------------------------|
| <u>FOR OFFICE USE ONLY</u> |
| Facility # 5-013932        |
| Permit # 00639-2015UPG     |
| Request Rec'd 07/09/2015   |
| Amended Date               |
| Approval Date 7/9/2015 DS  |
| Permit Expires 7/23/2015   |

**Permit for Emergency Repair Request on 07/08/2015**

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

|   |  |
|---|--|
| <p><b>(1) OWNER OF TANKS</b> - Corporation, partnership, or other business entity:<br/>         Wally Hutter Oil Company<br/>         P.O. Box 1006,<br/>         Quincy, IL 62301<br/>         Contact: David Smith (217) 285-5558</p> | <p><b>(2) FACILITY</b> - name and address where tanks are located:<br/>         State Street Shell<br/>         2400 State<br/>         Quincy, Adams Co., IL<br/>         Contact: Lanny Hintz (211) 223-6380</p> |
|---|--|

**(3) UPGRADE OR REPAIR OF TANKS:**

- (a) *Number and size of tanks being upgraded or repaired:* (TK # 10) - 12,000 gallons
- (b) *Type of tanks:*
- (c) *Type of piping:* (TK # 10) - (Installing) Partial Flexible Single Wall Piping to replace leaking nipple inside dispenser sump for dispenser 5/6
- (d) *Product to be stored in each tank:* (TK # 10) - Gasoline
- (e) *Type of leak detection being used:*  
     *Tank:*  
     *Piping:*
- (f) *Corrosion Protection being used:*  
     *Tank:*  
     *Piping:* (TK # 10) - (Installing) Flexible Non-Corrosive
- (g) *Spill containment devices, piping, and dispenser containment devices:*
- (h) *Overfill prevention devices:*
- (i) *Manway accessible at grade:*

**(4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.**

**(5) SPECIAL CONTINGENCIES:**

|  |  |
|--|--|
| <p><b>(6) PERSON, FIRM OR COMPANY PERFORMING WORK:</b></p>   |  |
| <p>R. L. Hoener Company<br/>         2923 Gardner Expressway, P. O. Box 1086<br/>         Quincy, IL 62305</p> | <p>Contact Person: Marty Jackson<br/>         Phone: (217) 223-2190<br/>         Contractor Registration # IL-2021 Exp. 05/22/2016</p> |

Sincerely,

Daniel Starks

cc: Storage Tank Safety Specialist -  
 Fire Department -  
 Division File  
 (Rev. - 9/10)