

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2026339 Permit # 01036-2015UPG Request Rec'd 09/28/2015 Amended Date Approval Date 9/29/2015 DS Permit Expires 3/29/2016

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Hemant Patel

3 Deveaux Court South Barrington, IL 60634

Contact: Hemant Patel (847) 331-1879

(2) FACILITY - name and address where tanks are located:

BP Amoco #18883 1100 West Stearns Road Bartlett, IL 60103

Contact: Rickey Uppal (630) 540-2132

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 4) 15,000, (TK # 6) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 4, 6) Piping Flexible Double Wall OPW Flexworks CP-15 non corrosive
- (d) Product to be stored in each tank: (TK # 4, 6) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Disconnecting and repairing the double wall flex pipe in the submersible sump on Tank 4 (East Regular).

Removing and replacing the entire Premium (Tank 6) pipe run between two east islands. Line had a previous repair performed on fittings inside an island dispenser sump. Repairs were not performed correctly and line must be replaced.

Omblis, Inc. 24325 Leski Lane Plainfield, IL 60585 Contact Person: Kiran Madhu Phone: (630) 649-8699 Contractor Registration # IL002410 Exp. 8/10/2017

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File