

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 6013612 Permit # 01197-2015UPG Request Rec'd 10/27/2015 Amended Date Approval Date 10/28/2015 DS Permit Expires 4/28/2016

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Gateway FS, Inc. 221 East Pine Street Red Bud, IL 62278

Contact: Greg Birchler (618) 282-3454

(2) FACILITY - name and address where tanks are located:

Gateway FS 9951 State Rt 127 Nashville, IL 62263

Contact: Brad Maschhoff (618) 713-4180

(3) **UPGRADE OR REPAIR OF TANKS:**

- (a) Number and size of tanks being upgraded or repaired: (TK # 4, 5) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 4, 5) Piping Fiberglass Single Wall Piping Ameron
- (d) Product to be stored in each tank: (TK # 4, 5) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

- 1) The master dispenser satellite feed line has no impact valve.
- 2) Remove dispenser, Saw cut and bust out concrete, dig out around flex connector.
- 3) Remove 24" flex connector and install new 18" flex connector.
- 4) Anchor flex connector and set dispenser back on island, pipe and wire up.
- 5) Perform nitorgen test with OSFM.

6) Backfill and pour concrete back in place.

Perform final inspection with OSFM.

If there is no existing sump, one must be installed

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Mid-South Steel Products, Inc. 2071 Corporate Circle Drive PO Box 277 Cape Girardeau, MO 63703 Contact Person: Billy Thorne Phone: (573) 335-5529

Contractor Registration # IL1194 Exp. 8/12/2016

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File