



Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety  
1035 Stevenson Drive  
Springfield, IL 62703  
2177851020

**FOR OFFICE USE ONLY**

Facility # 2016094  
Permit # 01219-2015UPG  
Request Rec'd 10/29/2015  
Amended Date  
Approval Date 11/2/2015 DS  
Permit Expires 5/3/2016

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

<p>(1) <b><u>OWNER OF TANKS</u></b> - Corporation, partnership, or other business entity:</p> <p>Mr. Haeger TR 7747 West Van Buren Street Forest Park, IL 60130</p> <p>Contact: Shuntitta Wallace (708) 496-7990</p>	<p>(2) <b><u>FACILITY</u></b> - name and address where tanks are located:</p> <p>United Parcel Service 16701 South Center Street Harvey, IL 60426</p> <p>Contact: Robert Elliott (312) 942-7582</p>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

**(3) UPGRADE OR REPAIR OF TANKS:**

(a) *Number and size of tanks being upgraded or repaired: (TK # 1) - 10,000*

(b) *Type of tanks:*

(c) *Type of piping: (TK # 1) Piping - Valves Ball Valve, (TK # 1) Piping - Submersible Sumps containment FRP, (TK # 1) Piping - Sumps Entry Boots*

(d) *Product to be stored in each tank: (TK # 1) - Gasoline*

(e) *Type of leak detection being used:*

*Tank:*

*Piping:*

(f) *Corrosion Protection being used:*

*Tank:*

*Piping:*

(g) *Spill containment devices, piping, and dispenser containmnt devices:*

(h) *Overfill prevention devices:*

(i) *Manway accessible at grade:*

(4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at [www.sfm.illinois.gov](http://www.sfm.illinois.gov) or by calling (217)785-1020.

**(5) SPECIAL CONTINGENCIES :**

**-Saw cut and break out concrete around existing piping sump manhole**

**-Provide vac truck to remove gravel from around existing tank top piping sump.**

**-Cut back existing product piping and conduits**

**-Remove existing submersible pump**


- Remove existing tank top piping sump with corroded tank adapter
- Install new OPW fiberglass sump with new tank adapter
- Install new submersible pump
- Hook to existing product piping and conduits and run into new sump
- Hook up new submersible pump and existing tank gauge equipment in sump
- Purge product and make sure of proper operation
- Backfill excavation
- Resurface with concrete

**(6) PERSON, FIRM OR COMPANY PERFORMING WORK:**

Accurate Tank Construction  
204 Poplar Place  
North Aurora, IL 60542

Contact Person: Jason Reed  
Phone: (630) 318-1813  
Contractor Registration # IL002360 Exp. 8/28/2016

Sincerely,

A handwritten signature in cursive script that reads "Daniel G. Starks". The signature is written in dark ink and is positioned above a horizontal line.

Daniel Starks

cc: Storage Tank Safety Specialist  
Division File