

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2014591 Permit # 01594-2016UPG Request Rec'd 12/21/2016 Amended Date Approval Date 12/21/2016 DS Permit Expires 6/21/2017

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

1 11/

Speedway, LLC P.O. Box 1500 Springfield, OH 45501

Springfield, OH 455011500

Contact: Eric Swaisgood (937) 863-6513

(2) FACILITY - name and address where tanks are located:

Speedway #7610 1975 Stunkel Road University Park, IL 60466

Contact: Tammy Wasnea (937) 863-6513

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 9) 8,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 9) Piping Shear Valves
- (d) Product to be stored in each tank: (TK # 9) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) SPECIAL CONTINGENCIES:

OPW 10 series double poppeted shear valve will not close. Need to replace with same OPW 10 Series shear valve double poppet.

Note there is containment under dispenser in place along with sensor. There is existing double wall fiberglass piping

(6)	PERSON.	<u>, FIRM OR</u>	<u>COMPANY</u>	<u> PERFORMING</u>	WORK:

DRW Services, Inc. 600 East Joe Orr Road Chicago Heights, IL 60411 Phone: (708) 758-3222 Contractor Registration # IL194 Exp. 3/10/2018

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File