

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2006651 Permit # 00166-2017UPG Request Rec'd 02/14/2017 Amended Date Approval Date 2/14/2017 DS Permit Expires 8/15/2017

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Dean Dairy Holdings, LLC

6303 Maxon Road Harvard, IL 60033

Contact: Charlie Vandebogart (815) 943-5441

(2) FACILITY - name and address where tanks are located:

Dean Illinois Dairies, LLC 6303 Maxon Road Harvard, IL 600338854

Contact: Wiz (Damian Wisowaty) (815) 943-5441

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 5) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 5) Piping Shear Valves
- (d) Product to be stored in each tank: (TK # 5) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Installing new shear valve in existing containment sump under dispenser.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108 Contact Person: Nate Meyer Phone: (815) 398-6250

Contractor Registration # IL1890 Exp. 3/7/2018

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File