

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

## FOR OFFICE USE ONLY

Facility # 2009072 Permit # 00027-2019UPG Request Rec'd 12/26/2018 Amended Date Approval Date 1/2/2019 DS Permit Expires 7/2/2019

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Oaklawn Mobil, Inc. 10240 S. Pulaski Rd	Oaklawn Mobil, Inc. 10240 S. Pulaski Rd. Oak Lawn, IL 60453
Contact: (708) 499-1869	Contact: Poulos Georgio (708) 499-1869

## (3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2, 3) Piping Other Steel Riser
- (d) Product to be stored in each tank: (TK # 1, 2) Gasoline Regular, (TK # 3) Gasoline Premium
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2, 3) Spill Contain Device Single Wall Spill Bucket OPW 1C-2100C-DEVR
- (h) Overfill prevention devices: (TK # 1, 2, 3) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO-400C
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Changing all 3 spill buckets, overfill valves and risers due to test fail changing to OPW 2100 series single wall, OPW 71SO overfill valve and changing risers from the top the tank disabling the ball float

## (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

America Petropump Services LLC d/b/a Ampsco Services 4075 Fox Valley Center Dr., Unit 9

Contact Person: Kiran Patibandla Phone: (630) 649-8699 Aurora, IL 60504

Sincerely,

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File