

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

Amended

FOR OFFICE USE ONLY

Facility # 4024443 Permit # 01381-2019UPG Request Rec'd 07/24/2019 Amended Date 07/24/2019 DS Approval Date 7/24/2019 DS Permit Expires 1/24/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Minit Mart, LLC 302 W. 3rd Street, Floor 3 Cincinnati, OH 45202

Contact: Toni VonRuden (513) 562-5738

(2) FACILITY - name and address where tanks are located:

Minit Mart McLean #799 401 S. Main Street McLean, IL 61754

Contact: Richard D. Horton (309) 874-2634

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3, 4) 8,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1, 2, 3) Gasoline, (TK # 4) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 1, 2, 3) Overfill Prev Device Overfill Drop Tube Valve OPW 61SOP, (TK # 4) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO-4000
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u>:

Permitting to **replace the failed ball float** vent valves for ID #1-2 with OPW 61SOP overfill drop tube valve assemblies due to failed testing of the vent valves. Replacing the ball float vent valve on ID #4 with OPW 71SO 4000 overfill drop tube valve assembly due to failed testing of the vent valve. Also replacing the ball float vent valve on ID #3 with OPW 61SOP overfill drop tube valve assembly to make facility uniform.

Upon ordering equipment for the permitted activity we were informed that the 61SOP drop tube valve for ID #4 (diesel) has been

discontinued. The part number will be 71SO 4000. The 61SOP valves for ID #1-2-3 are still manufactured and will be installed.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Total Petroleum Service Company 2421 Washington Road Washington, IL 61571 Contact Person: Greg McCoy Phone: (309) 694-8224

Contractor Registration # IL1079 Exp. 2/8/2020

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File