

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 6029334 Permit # 01431-2019UPG Request Rec'd 07/30/2019 Amended Date Approval Date 7/31/2019 DS Permit Expires 1/31/2020

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Midwest Petroleum Company 220 Old Meramec Station Rd.

Manchester, MO 63021

Contact: Tony Koenig (636) 220-3800

(2) FACILITY - name and address where tanks are located:

MPC #58

4001 S. State Rte. 159 Glen Carbon, IL 62034

Contact: Chuck Keller (800) 747-3777

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 5, 6) 6,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 5) E-85, (TK # 6) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 5, 6) Spill Contain Device Double Wall Spill Bucket Franklin Fueling Systems Defender 705
- (h) Overfill prevention devices: (TK # 5, 6) Overfill Prev Device Overfill Drop Tube Valve Franklin Fueling Systems 708 Defender Series
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

# (5) <u>SPECIAL CONTINGENCIES</u>:

Remove and install new EBW Defender series spill bucket and overfill drop tube on PNL and E-85 tamks only

Remove or disable Ball Floats for new compliance

## (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Parker Petroleum Sales and Service Inc. 1424 S Main Contact Person: Philip Parker Phone: (314) 401-5447 Ext. Phil Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File