

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

## **FOR OFFICE USE ONLY**

Facility # 2034129 Permit # 01446-2019UPG Request Rec'd 07/31/2019 Amended Date Approval Date 8/1/2019 DS Permit Expires 2/3/2020

## Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Thorntons LLC 2600 James Thornton Way Louisville, KY 40245

Contact: Shawn Orr (502) 425-8022

(2) FACILITY - name and address where tanks are located:

Thornton's, Inc. #118 15800 S. Route 59 Plainfield, IL 60544

Contact: Patricia Berens (502) 425-8022

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 3) 12,000, (TK # 4, 5) 6,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 3) E-85, (TK # 4, 5) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices:
- (h) Overfill prevention devices: (TK # 3, 4, 5) Overfill Prev Device Ball Only Removed Ball Float Vent Valve, (TK # 3, 4, 5) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Existing Ball Float cages are to be removed on Tank #3, #4, and #5. These three tanks also have another form of overfill protection (the OPW 71SO overfill drop tubes) and the drop tubes would need to be the form of device listed as the main form of overfill protection.

(6)	DEDCON	FIDM OD	COMBAND	PERFORMI	NC WODE
w	PERSON.	TIKNI UK	COMPANY	PERFURM	NG WUKN

Protanic, Inc. 658 North Progress Drive PO Box 80265 Contact Person: Frank Grebas Phone: (262) 268-1150 Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File