

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

#### **FOR OFFICE USE ONLY**

Facility # 2024913 Permit # 01655-2019UPG Request Rec'd 09/03/2019 Amended Date Approval Date 9/3/2019 DS Permit Expires 3/3/2020

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

First Student, Inc. 600 Vine Street, Suite 1400 Cincinnati, OH 45202

Contact: Susan Kirkpatrick (513) 419-8639

(2) FACILITY - name and address where tanks are located:

Illinois Central School Bus, LLC 3625 W. Washington Street Park City, IL 60085

Contact: Matt Finn (815) 409-4111

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 5) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 5) Piping Fiberglass Double Wall Ameron Dualoy 3000/LCX from tank to South fuel island only, (TK # 5) Piping Check Valves
- (d) Product to be stored in each tank: (TK # 5) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 5) Leak Detect - Piping - European with No Test Reg Suction

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 5) Spill Contain Device Single Wall Spill Bucket EBW 705
- (h) Overfill prevention devices: (TK # 5) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO-4000 NOTE: No existing ball float listed in our database
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Installing new APT LM2010 dispenser sump.

# (6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Petroleum Technologies Equipment, Inc. 8447 West 44th Place Lyons, IL 60534

Contact Person: Thomas Doherty Phone: (708) 426-0400 Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File