

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2019552 Permit # 01812-2019UPG Request Rec'd 09/23/2019 Amended Date Approval Date 9/23/2019 DS Permit Expires 3/24/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Buchanan Energy N, LLC 7315 Mercy Road Omaha, NE 68124

Contact: Kelly Bissias (402) 558-9860

(2) FACILITY - name and address where tanks are located:

Bucky's Express #416 9544 Waukegan Road Morton Grove, IL 60053

Contact: Joy Yama (402) 558-9860

(3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 11, 12, 13, 14) 10,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 11, 12) Gasoline Regular, (TK # 13) Gasoline Premium, (TK # 14) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 11, 12, 13) Spill Contain Device Single Wall Spill Bucket OPW 1-2100
- (h) Overfill prevention devices: (TK # 11, 12, 13, 14) Overfill Prev Device Ball Only Removed Ball Float Vent Valve, (TK # 11, 12, 13, 14) Overfill Prev Device Overfill Drop Tube Valve OPW 71SO-410C
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Removal of ball floats on all four tanks. Replacement of spill buckets on tanks 11, 12, 13 with OPW 1-2100 single wall spill buckets. Installation of overfill prevention drop tubes on all four tanks (OPW 71so-410c)

(6) PE	KSUN,	FIKM OK	COMPANY	PERFORM	/IIING V	WUKK:
--------	-------	----------------	---------	---------	----------	-------

Stenstrom Petroleum Services Group

Contact Person: Robert Stenstrom

Phone: (815) 398-6250 Contractor Registration # IL1890 Exp. 4/12/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File