

## Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

# **FOR OFFICE USE ONLY**

Facility # 2017671 Permit # 02007-2019UPG Request Rec'd 10/21/2019 Amended Date Approval Date 10/21/2019 DS Permit Expires 4/21/2020

#### Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

Speedway, LLC P.O. Box 1500

Springfield, OH 45501

Contact: Eric M. Swaisgood (937) 863-6513

(2) FACILITY - name and address where tanks are located:

Speedway #8327 701 E Lake Street Addison, IL 60101

Contact: Store Manager (630) 530-9652

## (3) <u>UPGRADE OR REPAIR OF TANKS:</u>

- (a) Number and size of tanks being upgraded or repaired: (TK # 4) 12,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 4) Piping Fiberglass Double Wall Ameron Dualoy 3000/LCX, (TK # 4) Piping Ball Valves
- (d) Product to be stored in each tank: (TK # 4) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 4) Spill Contain Device Double Wall Spill Bucket OPW 1C-3112P Edge
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

# (5) <u>SPECIAL CONTINGENCIES</u>:

Replace exisitng Remote Fill Line and Overspill manhole due to leak in line.

Will install new entry boot for new line with 3" and hydrostatic test existing fiberglass sump as well as new Overspill Manhole

NOTE: Remote fills over 20' in length shall have interstitial monitoring and an audible and visible overfill alarm per 175.445 f)

Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108 Contact Person: Robert Stenstrom Phone: (815) 398-6250 Contractor Registration # IL1890 Exp. 4/12/2020

Sincerely,

Daniel Starks

Daniel J. Starks

cc: Storage Tank Safety Specialist Division File