

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 2177851020

Amended

FOR OFFICE USE ONLY

Facility # 1014906 Permit # 02150-2019UPG Request Rec'd 11/08/2019 Amended Date 02/03/2020 DS Approval Date 11/12/2019 DS Permit Expires 5/12/2020

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
	Toedter Oil Company, Inc. 13120 IL Hwy 89 Granville, IL 61326
Contact: Eric Toedter (815) 664-2818	Contact: Carla Margis (815) 664-2818

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2, 3, 6, 7, 8, 10) 9,500, (TK # 4, 5) 11,500, (TK # 9) 14,500
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1, 2) Gasoline Regular, (TK # 3, 6) Gasoline Non Ethanol, (TK # 4, 5, 10) Diesel Fuel, (TK # 7) Kerosene, (TK # 8) B-11, (TK # 9) Dyed B-11
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containmnt devices: (TK # 1, 2, 3, 4, 5, 6, 7, 8, 9, 10) Spill Contain Device Single Wall Spill Bucket Horizontal Cabinet
- (h) Overfill prevention devices: (TK # 1, 2, 3, 4, 5, 6, 7, 8, 9, 10) Overfill Prev Device Overfill Alarm
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfmillinois.gov or by calling (217)785-1020.

(5) <u>SPECIAL CONTINGENCIES</u> :

Amendment Reason: Remote fill lines are rusted and not in very goodshape We excavated to the tops of the tanks and there are no ball floats installed on the vent lines.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Illinois Oil Marketing Equipment, Inc.

Phone: (309) 347-1819 Contractor Registration # IL1293 Exp. 2/4/2020

Sincerely,

Daniel J. Starke

Daniel Starks

cc: Storage Tank Safety Specialist Division File