

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2021131 Permit # 00393-2022UPG Request Rec'd 04/11/2022 Amended Date Approval Date 4/17/2022 DS Permit Expires 10/18/2022

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business

entity:

Morton Mini Mart 7736 W. Dempster Morton Grove, IL 60053

Contact: (847) 347-0047

(2) **FACILITY** - name and address where tanks are located:

Dempster Ozark Shell 7736 Dempster Morton Grove, IL 60053

Contact: Shila Chemmachel (847) 347-0047

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1, 2) 10,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1, 2) Piping Other Steel Riser, (TK # 1, 2) Piping Extractor Fitting Valves
- (d) Product to be stored in each tank: (TK # 1, 2) Gasoline Regular
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) **SPECIAL CONTINGENCIES**:

As Per NOV Tanks 1& 2 has failed triennial sump testing for the resons mentioned belowfor those 2 contimenments Protonic report mentioned us to repair them for retest

The extractor housing in rusted in tanks 1& 2 so replacing and redirecting the existing vent line inside an existing continuants and removing the sensor from containment that doesn't have any product piping. The vapor has a spill bucket so we are removing it by repacing it with a raiser for vapor adapter

Contact Person: Ravindra Penmatsa

Phone: (312) 286-6722

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

America Petropump Services LLC d/b/a Ampsco Services 4075 Fox Valley Center Dr., Unit 9

Sincerely, Daniel J. Starks

Daniel Starks

cc: Storage Tank Safety Specialist Division File