



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
2177851020

Amended

FOR OFFICE USE ONLY

Facility # 3025265
Permit # 00546-2022UPG
Request Rec'd 05/23/2022
Amended Date 06/21/2022 SB
Approval Date 5/23/2022 DS
Permit Expires 11/23/2022

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity: Thorntons LLC 2600 James Thornton Way Louisville, KY 40245 Contact: Maggie Seaguh (502) 425-8022	(2) FACILITY - name and address where tanks are located: Thornton Oil #351 107 Spring Creek Rd. East Peoria, IL 61611 Contact: Tammy Schreiber (309) 694-1777
--	--

(3) UPGRADE OR REPAIR OF TANKS:

- (a) *Number and size of tanks being upgraded or repaired: (TK # 12, 13, 14) - 10,000, (TK # 15, 16) - 6,000*
- (b) *Type of tanks:*
- (c) *Type of piping: (TK # 12, 13, 14, 16) Piping - Fiberglass Double Wall Ameron Dualoy 3000/L, (TK # 12, 13, 14) Piping - Flexible Double Wall OPW Flexworks*
- (d) *Product to be stored in each tank: (TK # 12) - Gasoline - Premium, (TK # 13) - E-85, (TK # 14, 16) - Diesel Fuel, (TK # 15) - Kerosene*
- (e) *Type of leak detection being used:*
 - Tank: (TK # 12, 13, 14, 16) Leak Detect - Tank - Non-Discriminating Interstitial Monitoring Sensors With Monitor*
 - Piping: (TK # 12, 13, 14, 16) Leak Detect - Piping - Electronic Pressurized Line Leak Detection, (TK # 16) Leak Detect - Piping - Siphon Bar*
- (f) *Corrosion Protection being used:*
 - Tank:*
 - Piping:*
- (g) *Spill containment devices, piping, and dispenser containment devices: (TK # 12, 13, 14, 16) Spill Contain Device - Double Wall Spill Bucket*
- (h) *Overfill prevention devices: (TK # 12, 13, 14, 15, 16) Overfill Prev Device - Overfill Drop Tube Valve*
- (i) *Manway accessible at grade:*

- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) SPECIAL CONTINGENCIES :

Removing ball float vent valve and replacing with overfill drop tube.


Amendment Reason: Change in equipment being used. Replacing partial piping on tanks 12, 13 & 14 to first dispenser sumps.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Seneca Companies, Inc.
4140 East 14th Street PO Box 3360

Contact Person: Glen Davis
Phone: (816) 761-1270

Sincerely,

A handwritten signature in cursive script that reads "Daniel G. Starks". The signature is written in dark ink and is positioned above a thin horizontal line.

Daniel Starks

cc: Storage Tank Safety Specialist
Division File