

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 7015259 Permit # 00972-2022UPG Request Rec'd 09/07/2022 Amended Date Approval Date 9/8/2022 DS Permit Expires 3/8/2023

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

(2) **FACILITY** - name and address where tanks are located:

I Khodal II, LLC 13381 Hamilton Pike Road Whittington, IL 62897 BP Benton Station 640 W. Main St. Benton, IL 62812

Contact: Bobby Patel (816) 807-0317

Contact: Bobby Patel (816) 807-0317

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 11) 4,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 11) Piping Flexible Double Wall A.P.T. Poly Tech P150SC
- (d) Product to be stored in each tank: (TK # 11) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) **SPECIAL CONTINGENCIES**:

Diesel product line was damaged by a drill rig. Excavate to the line where damaged and repair the chase pipe. Remove the existing product pipiong and pull in new product piping through the existing chase pipe. All existing equipment to be reused except for the product piping.

Replaced piping exceeds 20 feet or 50% of the total pipe run.

NOTE: Site has existing sumps and sensors

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

UPC Enterprises, LC d/b/a United Petroleum Service

Contact Person: Terry Smith

Phone: (314) 241-3767

Contractor Registration # IL002402 Exp. 2/10/2024

Sincerely,

Daniel Starks

Daniel J. Starke

cc: Storage Tank Safety Specialist Division File