

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 2041728 Permit # 00975-2022UPG Request Rec'd 09/08/2022 Amended Date Approval Date 9/8/2022 DS Permit Expires 3/8/2023

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

(2) <u>FACILITY</u> - name and address where tanks are located:

WELBIC III Aurora 3883, LIC 970 N. Oaklawn Ave., Ste 100 Elmhurst, IL 60126 FedEx Freight, Inc.-AUR 3883 Butterfield Rd. Aurora, IL 605026893

Contact: Kristie Moran (630) 782-9520

Contact: Matt Sonkovitch (630) 820-6429

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 20,000
- (b) Type of tanks:
- (c) Type of piping:
- (d) Product to be stored in each tank: (TK # 1) Diesel Fuel
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices: (TK # 1) Spill Contain Device Double Wall Spill Bucket
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) **SPECIAL CONTINGENCIES**: Replacing Single Wall Spill Bucket with Double Wall Spill Bucket.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Beacon SSI, Inc.

Contact Person: Patrick Ferriter
10526 W. Cermak Rd Suite 302

Phone: (708) 917-2263

Westchester, IL 60154 Contractor Registration # IL002336 Exp. 1/27/2023

Daniel J. Starks

Daniel Starks

cc: Storage Tank Safety Specialist Division File