

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 2177851020

FOR OFFICE USE ONLY

Facility # 4018731 Permit # 01068-2022UPG Request Rec'd 09/27/2022 Amended Date Approval Date 9/28/2022 DS Permit Expires 3/28/2023

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) <u>OWNER OF TANKS</u> - Corporation, partnership, or other business entity:

(2) $\underline{FACILITY}$ - name and address where tanks are located:

Effingham Equity 201 W. Roadway Ave. Effingham, IL 62401 Effingham Equity North 4th St. Effingham, IL 62401

Contact: Eddie Cavanah (217) 273-0887

Contact: Eddie Cavanah (217) 273-0887

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 1) 20,000
- (b) Type of tanks:
- (c) Type of piping: (TK # 1) Piping Steel Single Wall Piping
- (d) Product to be stored in each tank: (TK # 1) Gasoline Mid-grade
- (e) Type of leak detection being used:

Tank:

Piping:

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.

(5) **SPECIAL CONTINGENCIES**:

A leaking flex connector under dispenser 1/2 was discovered. IOME will break concrete in front of the island to uncover the product line. The flex will be removed and the line capped with a steel cap. The line being capped off will be tested to verify the rest of the line is sound. At that point the other dispensers can be re-opened for use of that product. The site has single wall steel piping and no containment. IOME is working on a quote to upgrade the system. Installing new tanks, containment and double wall piping.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Illinois Oil Marketing Equipment, Inc. 850 Brenkman Drive Pekin, IL 61554 Contact Person: Bryan Estes Phone: (309) 347-1819

Contractor Registration # IL1293 Exp. 2/4/2024

Sincerely,

Daniel Starks

Carrief J. Starks

cc: Storage Tank Safety Specialist Division File