



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY

Facility #: 2038253
Permit #: 00586-2023UPG
Request Rec'd: 06/01/2023
Approval Date: 06/04/2023 DS
Permit Expires: 12/05/2023

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Mac's Convenience Stores, LLC 1100 Situs Court, Suite 100 Raleigh, NC 27606 (None) County Contact: Elizabeth Patterson 984/389-1765	FACILITY - name and address where tanks are located: Circle K #1392 280 N. Kennedy Dr. Bradley, IL 60915 Kankakee County Contact: Tina Polito 815/933-3365
---	---

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
1	Diesel Fuel	10,000	Currently in use	Federal
2	Gasoline - Premium	10,000	Currently in use	Federal
3	Gasoline - Regular	10,000	Currently in use	Federal
4	Gasoline - Regular	10,000	Currently in use	Federal

Tank 1 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Ball Float Vent Valve EBW 308	Removing
Overfill Prevention Device	Overfill Drop Tube Valve	New

Tank 2 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Ball Float Vent Valve EBW 308	Removing
Overfill Prevention Device	Overfill Drop Tube Valve	New

Tank 3 Equipment

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Ball Float Vent Valve EBW 308	Removing
Overfill Prevention Device	Overfill Drop Tube Valve	New

Tank 4 Equipment

Equipment Type	Permit Equipment	Action
Spill Containment Device	Single Wall Spill Bucket	Removing
Spill Containment Device	Double Wall Spill Bucket	New
Overfill Prevention Device	Ball Float Vent Valve EBW 308	Removing
Overfill Prevention Device	Overfill Drop Tube Valve	New
Piping	Other Steel Riser	New

Summary of Work


Removing ball floats from all tanks and adding overfill drop tubes to all. Replacing spill container and riser on RUL2. Not adding any sensors but I could not get past that page without saying I was. The sensors in the tank sumps already exist.

Special Contingencies

Removing ball floats from all tanks and adding overfill drop tubes to all. Replacing spill container and riser on RUL2. Not adding any sensors but I could not get past that page without saying I was. The sensors in the tank sumps already exist.

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448	Contact Person: Ron Anderson Phone: 708/243-9081 Email: steve@andersonpump.com Contractor License # IL002275 Exp. 5/21/2024

Sincerely,



Daniel Starks