



**Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety**
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov
Amended

FOR OFFICE USE ONLY

Facility #: 2028273
Permit #: 00667-2023UPG
Request Rec'd: 06/20/2023
Amended Date: 07/20/2023 DS
Approval Date: 06/20/2023 DS
Permit Expires: 12/20/2023

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for
Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

| | |
|---|---|
| OWNER OF TANKS - Corporation, partnership, or other business entity: DKV Properties, LLC 321 Eli Barns Court Sycamore, IL 60178 (None) County Contact: Rakesh Patel 630/730-0187 | FACILITY - name and address where tanks are located: Dundee Shell 282 Dundee Ave. Elgin, IL 60120 Kane County Contact: SYED MIR 630/363-3530 |
|---|---|

Tanks on the Permit

| Tank # | Product | Capacity | Tank Status | Regulated Status |
|--------|--------------------|----------|------------------|------------------|
| 2 | Gasoline - Premium | 10,000 | Currently in use | Federal |

Tank 2 Equipment

| Equipment Type | Permit Equipment | Action |
|----------------|----------------------|--------|
| Piping | Flex Connector Steel | New |

Summary of Work

Inside Premium STP, there is a small leak detected in Flex pipe. We are replacing the flex pipe with new Flex. Also taking care of the existing NOV dispenser 6 hose by replacing with new hose. Since we are not able to find the leak we are trenching the 20 feet to find any leaks in premium line towards pumps from STP. If we are not able to find any leak after trenching we will pour back the concrete.

Thank you
Innovative Team

Special Contingencies

Amendment Reason:

Not able to find the leak with flex inside the STP

| | |
|---|---|
| PERSON, FIRM OR COMPANY PERFORMING WORK: | |
| Innovative Constructions Technology LLC 245 W Roosevelt Rd Building 4, Unit 28 West Chicago, IL 60185 | Contact Person: Raju penumatsa Phone: 630/747-3404 Email: iconstructions81@gmail.com Contractor License # IL002453 Exp. 2/7/2024 |

Sincerely,

Daniel Starks

