

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov FOR OFFICE USE ONLY

Facility #: 7021575
Permit #: 01269-2023UPG
Request Rec'd: 10/31/2023
Approval Date:11/01/2023 DS
Permit Expires: 05/01/2024

<u>Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances</u>

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS

- Corporation, partnership, or other business entity:

Veera Ashvi, LLC 500 W. 10th Street Metropolis, IL 62960 Massac County

Contact: Julie Patel 618/634-9630

FACILITY

- name and address where tanks are located:

Pickup Mart

Route 169 & Route 37 Karnak, IL 62956 Pulaski County

Contact: Beena Patel 618/634-9630

Dispensers on the Permit

Dispenser	Action
1/2	Sump / Sensors Changing

Dispenser 1/2 Equipment

Equipment Type	Permit Equipment	Action
Dispenser	Single Wall UDC Sump	New

Special Contingencies

PERSON, FIRM OR COMPANY PERFORMING WORK:

Neumayer Equipment Company, Inc.

5060 Arsenal Street St. Louis, MO 63139 Contact Person: Jimmy Spiros

Phone: 314/772-4501

Email: testing@neumayerequipment.com Contractor License # IL1502 Exp. 3/26/2024

Sincerely,

Daniel Starks

For Office Use Only

Dispenser 1/2 Equipment

Caniel J. Stark

Equipment Type	Permit Equipment	Action
Dispenser	Not Installed UDC Sump	Removing