



**Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety**  
1035 Stevenson Drive  
Springfield, IL 62703  
217/785-1020  
www.sfm.illinois.gov  
SFM.DPCS@illinois.gov

**FOR OFFICE USE ONLY**

Facility #: 2006940  
Permit #: 00076-2024UPG  
Request Rec'd: 01/22/2024  
Approval Date: 01/22/2024 DS  
Permit Expires: 07/23/2024

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for  
Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

**THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

|   |  |
|---|--|
| <b>OWNER OF TANKS</b><br>- Corporation, partnership, or other business entity:<br>Crown Properties Enterprise, Inc.<br>3553 W. 159th Street<br>Markham, IL 60426<br>Cook County<br>Contact: Aqil Jaade 713/791-1670 | <b>FACILITY</b><br>- name and address where tanks are located:<br>Maple Petroleum<br>3553 W. 159th St.<br>Markham, IL 60426<br>Cook County<br>Contact: Aqil Jaade 773/791-1670 |
|---|--|

**Tanks on the Permit**

| Tank # | Product            | Capacity | Tank Status      | Regulated Status |
|--------|--------------------|----------|------------------|------------------|
| 6      | Gasoline - Premium | 10,000   | Currently in use | Federal          |

**Tank 6 Equipment**

| Equipment Type             | Permit Equipment      | Action   |
|----------------------------|-----------------------|----------|
| Overfill Prevention Device | Ball Float Vent Valve | Removing |

**Summary of Work**

Knock out ball float from premium tank extractor - overfill flapper uses as overfill method

**Special Contingencies**

|  |   |
|--|---|
| <b>PERSON, FIRM OR COMPANY PERFORMING WORK:</b>                                |   |
| Stenstrom Petroleum Services Group<br>2422 Center Street<br>Rockford, IL 61108 | Contact Person: Robert Stenstrom<br>Phone: 815/398-6250<br>Email: amberp@rstenstrom.com<br>Contractor License # IL1890 Exp. 4/12/2024 |

Sincerely,

Daniel Starks