



Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov
Revised/Amended

FOR OFFICE USE ONLY	
Facility #:	2019053
Permit #:	01470-2024UPG
Request Rec'd:	11/15/2024
Approval Date:	11/15/2024 DS
Amended Date:	11/26/2024 DS
Revision Date:	12/02/2024 DS
Permit Expires:	05/15/2025

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

OWNER OF TANKS - Corporation, partnership, or other business entity: Chicago Title Land Trust 113786-01 (Indian Head Transit Company) 3211 Howard Street Skokie, IL 60076 Cook County Contact: Anthony Benish 708/560-9840	FACILITY - name and address where tanks are located: North Shore Transit, Inc. 3211 Howard Street Skokie, IL 60076 Cook County Contact: Brian Evans 847/677-9700
---	---

Tanks on the Permit

Tank #	Product	Capacity	Tank Status	Regulated Status
2	Gasoline - Regular	10,000	Currently in use	Federal

Tank 2 Equipment

Equipment Type	Permit Equipment	Action
Piping	Flex Connector Steel	New

Summary of Work

Repairing kinked flexible product piping inside of dispenser sump. No replacement of sump or any piping is now necessary

Special Contingencies

Amendment Reason:

Ended up not needing to remove and replace under dispenser sump to make piping repair

Amendment Reason:

Ended up not needing to remove and replace under dispenser sump to make piping repair

Revision Reason:

No precision test is needed being as how it's European suction

PERSON, FIRM OR COMPANY PERFORMING WORK:	
Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108	Contact Person: Robert Stenstrom Phone: 630/878-6354 Email: Jasonre@rstenstrom.cm Contractor License # IL1890 Exp. 4/12/2026

Sincerely,

Daniel J. Starks

Daniel Starks