



**Office of the Illinois State Fire Marshal  
Division of Petroleum and Chemical Safety**  
1035 Stevenson Drive  
Springfield, IL 62703  
217/785-1020  
www.sfm.illinois.gov  
SFM.DPCS@illinois.gov  
**Amended**

FOR OFFICE USE ONLY	
Facility #:	3009229
Permit #:	00322-2025UPG
Request Rec'd:	03/19/2025
Approval Date:	03/19/2025 DS
Amended Date:	03/31/2025 DS
Permit Expires:	09/19/2025

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for  
Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

**THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.**

<b>OWNER OF TANKS</b> - Corporation, partnership, or other business entity: Gold Star FS, Inc. 13125 IL Hwy 81 Cambridge, IL 61238 Henry County Contact: Ethan Washburn 815/499-9766	<b>FACILITY</b> - name and address where tanks are located: Annawan Fuel 24 Rt 78 - North Canal St Annawan, IL 61234 Henry County Contact: Ethan Washburn 309/937-3369
--	--

**Tanks on the Permit**

Tank #	Product	Capacity	Tank Status	Regulated Status
2	B-11	10,000	Currently in use	Federal
3	Gasoline - Regular	10,000	Currently in use	Federal

**Tank 2 Equipment**

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Overfill Drop Tube Valve	Replacing - Overfill Prev Device - Ball Float Vent Valve
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

**Tank 3 Equipment**

Equipment Type	Permit Equipment	Action
Overfill Prevention Device	Overfill Drop Tube Valve	Replacing - Overfill Prev Device - Ball Float Vent Valve
Spill Containment Device	Double Wall Spill Bucket	Replacing - Spill Contain Device - Single Wall Spill Bucket

**Summary of Work**

Replacing existing single wall spill bucket with new grade level double wall spill bucket.

**Special Contingencies**

**Amendment Reason:**

We removed the existing Ball Floats and installed new EBW Defender Dual Point overfill valves in the new EBW Defender Double walled spills.

<b>PERSON, FIRM OR COMPANY PERFORMING WORK:</b>	
Pipeco, Inc. 610 29th Street Bettendorf, IA 52722	Contact Person: Robert Schafer Phone: 563/344-0700 Email: rob@pipecoinc.com Contractor License # IL2034 Exp. 9/28/2026

Sincerely,

*Daniel J. Starks*

Daniel Starks