



**Office of the Illinois State Fire Marshal
Division of Petroleum and Chemical Safety**
1035 Stevenson Drive
Springfield, IL 62703
217/785-1020
www.sfm.illinois.gov
SFM.DPCS@illinois.gov

FOR OFFICE USE ONLY
Facility #: 2007202
Permit #: 00434-2025UPG
Request Rec'd: 04/09/2025
Approval Date: 04/11/2025 DS
Permit Expires: 10/14/2025

**Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for
Petroleum and Hazardous Substances**

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

| | |
|---|---|
| OWNER OF TANKS - Corporation, partnership, or other business entity: Williams Hayward Protective Coatings, Inc. 5241 West 70th Place Bedford Park, IL 60638 Cook County Contact: Thomas Kurcz 708/563-5184 | FACILITY - name and address where tanks are located: Williams Hayward Protective Coating 5241 W. 70th Place Bedford Park, IL 60638 Cook County Contact: Tommy Kurcz 708/218-7589 |
|---|---|

Tanks on the Permit

| Tank # | Product | Capacity | Tank Status | Regulated Status |
|--------|---------------------|----------|------------------|------------------|
| 20 | Hazardous Substance | 1,200 | Currently in use | Federal |
| 21 | Texanol | 1,200 | Currently in use | Federal |
| 22 | Butyl Cellosolve | 1,200 | Currently in use | Federal |
| 23 | Mineral Spirits | 1,200 | Currently in use | Federal |
| 24 | Dibutyl Phthalate | 1,200 | Currently in use | Federal |
| 25 | Methyl Carbitol | 1,200 | Currently in use | Federal |
| 26 | Tolulol | 1,000 | Currently in use | Federal |
| 27 | Morpholine | 1,000 | Currently in use | Federal |
| 28 | n-Butyl Alcohol | 1,000 | Currently in use | Federal |
| 29 | Hazardous Substance | 1,000 | Currently in use | Federal |

Tank 20 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 21 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 22 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 23 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 24 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 25 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 26 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 27 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 28 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |

Tank 29 Equipment

| Equipment Type | Permit Equipment | Action |
|--------------------------|--------------------------|---|
| Spill Containment Device | Double Wall Spill Bucket | Replacing - Spill Contain Device - Single Wall Spill Bucket |


Summary of Work

Replacing all single wall spill buckets with OPW Edge Double-wall Spill buckets.

Special Contingencies

| PERSON, FIRM OR COMPANY PERFORMING WORK: | |
|---|--|
| Beacon SSI, Inc. 10526 W. Cermak Rd Suite 302 Westchester, IL 60154 | Contact Person: Patrick Ferriter Phone: 708/917-2263 Email: patrick.ferriter@beaconssi.com Contractor License # IL002336 Exp. 1/27/2027 |

Sincerely,



Daniel Starks