

Office of the Illinois State Fire Marshal Division of Petroleum and Chemical Safety 1035 Stevenson Drive Springfield, IL 62703 217/785-1020 www.sfm.illinois.gov SFM.DPCS@illinois.gov

 FOR OFFICE USE ONLY

 Facility #:
 2001729

 Permit #:
 00555-2025UPG

 Request Rec'd:
 05/08/2025

 Approval Date:05/08/2025 DS
 DS

 Permit Expires:
 11/10/2025

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to shall establish a date and time certain to perform the UST activity by scheduling the permitted activity through their UST contractor portal account. All testing forms must be submitted prior to the final being conducted.

THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE.

| OWNER OF TANKS - Corporation, partnership, or other business entity: | FACILITY - name and address where tanks are located: |
|---|--|
| RDK Ventures, LLC 1120 W. Warner Rd. Tempe, AZ 85284 (None) County | Circle K #6865 2 North Main Street Algonquin, IL 60102 McHenry County |
| Contact: Michele Alvarado 773/456-5280 | Contact: Christina Jacobo 331/251-7343 |

Tanks on the Permit

| Tank # | Product | Capacity | Tank Status | Regulated Status |
|--------|--------------------|----------|------------------|-------------------------|
| 1 | Gasoline - Regular | 12,000 | Currently in use | Federal |

Tank 1 Equipment

| Equipment Type | Permit Equipment | Action |
|-------------------------------|---|--|
| Overfill Prevention Device | Overfill Drop Tube Valve | Replacing - Overfill Prev Device - Overfill Drop Tube Valve |
| Piping | Other Steel Riser - New Vapor Riser | New |
| Piping | Other Steel Riser - New Fill Riser | New |
| Spill Containment Device | Double Wall Spill Bucket Replacing - Spill Contain Device - Double Wall Spill Bucket | |

Summary of Work

Installing new Fill riser and Vapor riser. Replacing Overspill bucket and Overfill drop tube on Regular Tank # 1

Special Contingencies

| PERSON, FIRM OR COMPANY PERFORMING WORK: | | | |
|--|--|--|--|
| Anderson Pump Service, Inc. 19659 South 97th Avenue Mokena, IL 60448 | Contact Person: Ron Anderson Phone: 708/560-5590 Email: Keith@Andersonpump.com Contractor License # IL002275 Exp. 5/21/2026 | | |

Sincerely,

Janiel J. Starke

Daniel Starks