

OFFICE OF THE ILLINOIS STATE FIRE MARSHAL

Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)785-1020

FOR OFFICE USE ONLY

Facility # 1-011001
Permit # 00711-2013ENT
Request Rec'd 07/24/2013
Amended Date
Approval Date 7/24/2013 DS
Permit Expires 1/24/2014

Permit for HOTWORK / ENTRY into Underground Storage Tank(s) for Petroleum and Hazardous Substances.

Permission to enter underground storage tank(s) is hereby granted. Such tank entry shall not commence until the contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall establish a date certain to perform the UST activity by contacting the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety, by telephone at the Springfield office between 8:30 a.m. and 12:00 p.m., at which time a mutually agreed upon date and time for the UST activity shall be scheduled. **THIS PERMIT IS VALID FOR SIX MONTHS FROM THE APPROVAL DATE**.

(1) **OWNER OF TANKS** - Corporation, partnership, or other

business entity:

Ilinois Toll Highway Authority 2700 Ogden Avenue, Downers Grove, IL 60515

Contact: Tom Deldin (708) 505-0703

(2) **FACILITY** - name and address where tanks are located:

ISTHA M07 Maint. Garage

Business 20 & I-90, Northwest Tollway, Mile Post 63.5

Rockford, Winnebago Co., IL

Contact: Laurie Nielsen (815) 399-2882

(3) ENTRY OF TANKS:

- (a) Number and size of tanks being entered: (TK # 2) 10,000 gallons
- (b) Type of tanks:
- (c) Product stored in each tank: (TK # 2) Diesel Fuel
- (d) Reason for tanks being entered: Tank was damaged during excavation work for a different tank. Tank to be repaired.
- (e) Manway accessible at grade: No
- (4) The owner must notify this Office when completion of tank entry has occurred, on the Notification for Underground Storage Tank Form. This form can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Tank relining, lining inspection and entry permit work in reference to manways/manholes must abide by section 175.500. Tank was damaged during excavation. A representative of the tank manufacturing company must be present while doing repairs to tank.

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Stenstrom Petroleum Services Group 2422 Center Street

Rockford, IL 61108

Contact Person: Nate Meyer Phone: (815) 398-6250

Daniel J. Starke

Contractor Registration # IL-1890 Exp. 03/07/2014

Sincerely,

Daniel Starks

cc: Storage Tank Safety Specialist - Fire Department -

Division File (Rev. - 9/10)