

OFFICE OF THE ILLINOIS STATE FIRE MARSHAL

Division of Petroleum and Chemical Safety

1035 Stevenson Drive Springfield, Illinois 62703-4259 (217)785-1020

FOR OFFICE USE ONLY

Facility # 2-021113
Permit # 00755-2013UPG
Request Rec'd 08/02/2013
Amended Date
Approval Date 8/2/2013 JC
Permit Expires 2/2/2014

Permit for UPGRADE or REPAIR of Underground Storage Tank(s) and Piping for Petroleum and Hazardous Substances.

Permission to upgrade or repair underground storage tank(s) or piping is hereby granted. Such upgrade or repair must be in complete accordance with acceptable materials as specified in the Federal Register, Part II Environmental Protection Agency, 40 CFR Parts 280 and 281, and also with all sections of 41 Illinois Administrative Code, Parts 174, 175 and 176. The contractor the permit was issued to or an employee of that contractor (this does not include a subcontractor) shall submit a required job schedule for underground piping upgrade, leak detection, spill and overfill prevention of underground storage tank(s) to the Office of the State Fire Marshal, Division of Petroleum and Chemical Safety.

(1) OWNER OF TANKS - Corporation, partnership, or other business entity:	(2) <u>FACILITY</u> - name and address where tanks are located:
Riteline Properties, LLC 200 W. Higgins Rd. Schaumburg, IL 60195	Shell 4758 River Rd. Schiller Park, Cook Co., IL
Contact: Nasir Yaquoob (847) 361-5927	Contact: Martha Mooses (630) 276-4262

(3) UPGRADE OR REPAIR OF TANKS:

- (a) Number and size of tanks being upgraded or repaired: (TK # 7) 20,000 gallons, (TK # 8) 12,000 gallons
- (b) Type of tanks:
- (c) Type of piping: (TK # 7, 8) (Installing) partial Fiberglass Double Wall Ameron Dualoy 3000/LCX from a new transition sump to two new dispensers (see site plan for location / details), (TK # 7, 8) (Installing) Transition Sump FRP fiberglass (see site plan for location / details). An existing island will be eliminated see site plan (a removal permit will NOT be necessary for this). Note also: there is existing piping that will remain in service that travels from the new transition sump to supply the existing northern most island (see permit #00756-2013INS for further details). Permit #00876-2005INS indicates all existing piping is DW fiberglass with interstitial sensors at each submersible sump and at all existing dispenser sumps.
- (d) Product to be stored in each tank: (TK # 7, 8) Gasoline
- (e) Type of leak detection being used:

Tank:

Piping: (TK # 7, 8) - (Installing) Piping Sump Sensors Interstitial Monitoring Veeder Root TLS 350 at the two new dispenser sumps and at the new transition sump.

(f) Corrosion Protection being used:

Tank:

Piping:

- (g) Spill containment devices, piping, and dispenser containment devices:
- (h) Overfill prevention devices:
- (i) Manway accessible at grade:
- (4) The owner must notify this Office when completion of tank upgrade/repair has occurred, on the Notification for Underground Storage Tank Form and the licensed contractor must submit the required job schedule for underground piping upgrade, leak detection, spill and overfill prevention to the OSFM prior to the work being performed. Both forms can be obtained at www.sfm.illinois.gov or by calling (217)785-1020.
- (5) <u>SPECIAL CONTINGENCIES</u>: Also, see permit #00756-2013INS for further details of work being done at this site.

Jame of Coffey

(6) PERSON, FIRM OR COMPANY PERFORMING WORK:

Stenstrom Petroleum Services Group 2422 Center Street Rockford, IL 61108 Contact Person: Nate Meyer Phone: (815) 398-6250

Contractor Registration # IL-1890 Exp. 03/07/2014

Sincerely,

Jim Coffey

Fire Department - Division File (Rev. - 9/10)